


Assembly instruction
Model 2050; 2064; 2066; 2068; 2076
XVHJ-CO-CFH




XVHJ-CO-CFH

LEGS

A

A x 4



B x 6

0R6K



D x 1

03-000587



E x 2

WSI M6x20


05-000824



F x 1

L4

05-001139



Assembly Legs A

POD 35
05-002209
x1


5,0x25
05-001064
x 4

5,0x25
05-001064
x 4

5,0x40
05-000748
x 3


5,0x25
05-001064
x4

5,0x25
05-001064
x4



Assembly Legs B



Assembly Legs C



1st XVHJ




IF THE SURFACE IS UNEVEN
ADDITIONAL PADS SHOULD BE
PLACED BETWEEN LEG AND SOFA





x2

2nd CO





3th CFH







x 3
POD 35
05-002209



IF THE SURFACE IS UNEVEN
ADDITIONAL PADS SHOULD BE
PLACED BETWEEN LEG AND SOFA



Assembly instruction
Model 2050; 2064; 2066; 2068; 2076
CV-CH



CV-CH

LEGS





A x 4




B x 0

0R6K




Assembly Legs A


POD 35
05-002209
x1




5,0x25
05-001064
x 4




5,0x25
05-001064
x 4




5,0x40
05-000748
x 3




5,0x25
05-001064
x4




5,0x25
05-001064
x4



Assembly Legs B



Assembly Legs C




1st CH





arm $\geq 20\text{cm}$
INSTALL AN ADDITIONAL LEG

B



x2




2nd CV




arm $\geq 20\text{cm}$
INSTALL AN ADDITIONAL LEG





Assembly instruction
Model 2050; 2064; 2066; 2068; 2076
CV-CFH




CV-CFH

LEGS

A

A x 4




B x 2

0R6K



D x 1



03-000587




E x 2
WSI M6x20
05-000824




F x 1
L4
05-001139



CV




CFH




Assembly Legs A


POD 35
05-002209
x1




5,0x25
05-001064
x 4




5,0x25
05-001064
x 4




5,0x40
05-000748
x 3




5,0x25
05-001064
x4




5,0x25
05-001064
x4



Assembly Legs B



Assembly Legs C





1st CV






arm $\geq 20\text{cm}$
INSTALL AN ADDITIONAL LEG

B




x2

2nd CFH



Assembly instruction
Model 2050; 2064; 2066; 2068; 2076
CFV-CO-UH



CFV-CO-UH

LEGS



A x 6



B x 4

0R6K



D x 1

03-000587



E x 2

WSI M6x20


05-000824



F x 1


L4

05-001139




Assembly Legs A


POD 35
05-002209
x1



5,0x25
05-001064
x 4




5,0x25
05-001064
x 4




5,0x40
05-000748
x 3



5,0x25
05-001064
x4




5,0x25
05-001064
x4




Assembly Legs B



Assembly Legs C



1st UH



x2



B



B

A



A




A





A




2nd CO



3th CFV



Assembly instruction
Model 2050; 2064; 2066; 2068; 2076
BV-HJXH




BV-HJXH

LEGS





A x 4





B x 4

0R6K



BV



HJXH

Assembly Legs A

POD 35
05-002209
x1


5,0x25
05-001064
x 4

5,0x25
05-001064
x 4

5,0x40
05-000748
x 3


5,0x25
05-001064
x4

5,0x25
05-001064
x4





Assembly Legs B

Assembly Legs C



1st HJXH




IF THE SURFACE IS UNEVEN
ADDITIONAL PADS SHOULD BE
PLACED BETWEEN LEG AND SOFA

2nd BV




arm $\geq 20\text{cm}$
INSTALL AN ADDITIONAL LEG



x 3
POD 35
05-002209



IF THE SURFACE IS UNEVEN
ADDITIONAL PADS SHOULD BE
PLACED BETWEEN LEG AND SOFA

4 x
5,0x25
05-001064

