


1 people

Assembly instruction 3001 with gaslift or without gaslift








A x 4
M8x20 C
05-000980




C x 1
6L
05-001043



Without gaslift

3



With gaslift

4

